

Briton
#1
door hardware choice

Briton
ALLEGION 

 **#1briton**
www.allegion.com/uk
Technical Support
T: 0800 834102

Fire Door Gap Tester

A maximum gap of **3mm** is recommended around all fire doors.

Use this card to assess the gap between the door leaf and the frame to check that your fire doors are fire safe.

(If in doubt contact the door manufacturer for further advice)

